

# Float & Splice Box Wiring Diagram




Oreco Systems<sup>®</sup>  
Incorporated

814 AIRWAY AVENUE  
SUTHERLIN, OREGON  
97479-9012


TELEPHONE:  
(541) 459-4449

FACSIMILE:  
(541) 459-2884


## Float Arrangement



## Float Types



## Splice Box Wiring



**Cord Grip**  
Hand tighten each cord grip  
so that the cord will not easily  
slide through the grommet.

## Float Tag Colors

- |                   |                   |
|-------------------|-------------------|
| <b>Y</b> - Yellow | <b>R</b> - Red    |
| <b>P</b> - Purple | <b>O</b> - Orange |
| <b>B</b> - Blue   | <b>E</b> - Grey   |
| <b>G</b> - Green  | <b>W</b> - White  |

## Key

- Black Wire
- White Wire
- Green Wire
- Waterproof Wire Nut
- Heat Shrink & Butt Connector \*

**Attention:** Failure to follow splicing instructions will void warranty

\* Refer to drawing EIN-SB-SB-1 for splicing instructions.

Note: In systems which include floats, this drawing replaces drawing no. "EDW-FA-S-1"

Note: Multi-function floats will have more than one marker

Control Panel Series

**S**

Float Function Color Code

**YBR**

Splice Box Model

**SB4**

Drawing No.

**EDW-FS-S-5**

EDW-FS-S-5  
Rev 1.1 ©03/15/11